



---

# **Landsat 7 Flight Operations Status (Spacecraft and MOC)**



# Landsat 7 Spacecraft and Ops Events

---

- 10/11/00 (Day 285) Delta-Inclination maneuver successfully completed, start time 13:52:40Z, duration 1172.3 seconds.
- 11/17/00 - 11/18/00 (Days 322, 323) Spacecraft passed through the Leonid storm without incident.
- 11/20/00 (Day 325) - “Lights Out” operations began.
- 12/25/00 (Day 360) - Spacecraft passed through the Moon’s shadow on two back-to-back orbits. Overall power balance and configuration was normal at the end of each orbit.
- 12/27/00 (Day 362) RTCS table in Flight Software was updated with new “end-of-year” RTCS values in preparation for 01/01/01.
- 12/31/00 (Day 366) - End of year operations completed successfully on SCP1.
- 01/10/01 (Day 10) End of year operations completed successfully on SCP2.



# Landsat 7 Spacecraft and Ops Events (cont.)

---

02/09/01 (Day 040) - Added coordinates in FSW on both SCPs for DSN testing (Canberra).

02/11/01 (Day 042) to 02/13/01 - SSR PWA #12 anomaly and recovery . See anomaly section for details.

03/05/01 (Day 064) - CIU Buffer Busy” anomaly - no interruption to operations. See anomaly section for details.


04/10/01 (Day 100) - Changed the gyro channel used for Roll information in Backup ACS modes (GCYAW) from Xa to Xb.

04/11/01 (Day 101) - Uplinked a patch to SSR RAM that will allow blocks to be “renamed” into areas that contain blocks that already “exist”.

05/11/01 (Day 131) - Added coordinates in FSW on both SCPs for Matera, Italy




# ETM+ Utilization : Lifetime Trend





# ETM+ Utilization: April-June 2001





# Landsat 7 Spacecraft Current Status

---

- Spacecraft Hardware and Software remains in the same configuration found at the end of the on-orbit checkout period except for the following:
  - Downlink site additions
  - RTCS updates
  - Time/year parameters
  - ESA Sun interference report timing
  - Gyro channel used for Roll data/control when in Backup modes switched from Xa to Xb
  - SSR RAM patches for hk dumps, TDF-SSR anomaly, and SSR-Rename anomaly
  - PRADS reset limit for unidentified stars
  - Celestial Star Sensor (CSA) alignment matrix
  - Maneuver abort limit due to attitude errors
  - SSR PWA #23 and #12 not in use
- Spacecraft orbit continues to meet specifications. To date, 45 orbit raising burns and 2 inclination raising burns have been completed.
- **Spacecraft performance and operation is nominal.** Mission objectives are being met and there are no indications of this changing in the near-term.



# Landsat 7 Spacecraft Anomalies

---

## **02/11/01 (Day 042) - SSR PWA #12 shutdown without being commanded.**

- “Loss of modulation” reported by LGS operator. Investigation showed a failure of SSR PWA #12.
- 02/12/01 (Day 043) - Switched to “Realtime imaging” only.
- 02/13/01 (Day 044) - SSR PWA #12 removed from service. Normal operations resumed.

## **03/05/01 (Day 064) - CIU Buffer Busy.**

- During loading of the daily stored command load, FSW calculated a different checksum for the load than the scheduling system. In addition, the “CIU Buffer Busy” condition was indicated by the spacecraft.
  - Load was rebuilt (although original load was valid) and uplinked at next contact without incident. No interruption to operations.
  - Investigation (including a dump of FSW before any more loads were uplinked) revealed that an extra 16 bits had been “inserted” into the command stream at the CIU/SCP interface. The CIU declared itself “busy” during a word transfer, and the SCP/FSW seemingly “double read” the previous word.
  - Currently, no root cause can be found. Active investigation closed.
-



# Landsat 7 On-Going Investigations/Efforts

---

## **The Flight Ops Team is working on several ongoing investigations/efforts...**

SSR -

- Implementation of the second patch is complete. Operational testing is ongoing. Preliminary results are good.
- Generation of SSR PWA board activation procedures is underway.

Battery Pressure - Procedures for possible use in lowering pressure (in an anomaly situation) are being generated. (see plot)

ETM+ Turn Around Time (TAT) - No change from last month. (see plot)

ETM+ duty cycle - Possible changes to LTAP may affect ETM+ use.

Investigation into gyro bias changes for Gyro #2 continues. Other users of this IMU package have been consulted. MGS and NOAA-15 reports being reviewed. Bias seems to be settling. (See plots)






# Landsat 7

## On-Going Investigations/Efforts

Maximum Battery Pressures






# Landsat 7

## On-Going Investigations/Efforts


### ETM+ Scan Time (from IAS web site)



# Landsat 7

## On-Going Investigations/Efforts

### Gyro Bias (for the three operational channels)






# Landsat 7


## On-Going Investigations/Efforts

### Gyro Bias (for the three operational channels)






# Landsat 7 Orbit and Expendables





# Landsat 7 Orbit and Expendables





---

# MOC Status



# MOC Status

---

- Current MOC Status...
  - MOC hardware and software are **Green** and able to support operations.
- Landsat 7 On-Orbit Flight Automation (LOOFA) Status (June)
  - 107 automated passes scheduled during June 2001.
  - 105 automated passes successfully completed.
  - 2 automated passes not completed due to command problems at sites.

## **Selected System pages :**

Most “pages” were generated in response to line outages between the MOC and ground site, and PTP or other connections problems at the sites.





# Upcoming Activities (next 3 months)

---

## ■ S/C

- Begin planning for Delta-i #3
- Dust off Leonid plan

## ■ MOC

- IPM web tool integration on IGS NT Server and interface to the MOC scheduling system
- Version Manager (VM) testing